	C	1	
Турє	י דח י	ıncıc	en
' 1 P			

Foot Injury

Summary:

Whilst using a torque wrench to tighten up a valve the employee felt back pain below his shoulder blade.

No Pictures available

Root Causes:

 The equipment provided / used was not suitable for this task

Actions Taken Thus Far: Next Steps

- Review risk assessment / Procedure for task and amend accordingly
- research for the most appropriate tooling to use for this type of activity
- Communicate and retrain all employees involved in this task, emphasising the importance in using the correct equipment and adhering to safe work practices

