

Location Country: Italy

Type of incident: cutting of a 15 kV electrical cable

**Summary:**

During the partitioning of underground sewers, an alleged disused pipe that interfered was cut with an isolated tool; the Person did not suffer damage, but there was a power failure: inside that conduit there was a live 15 kV electrical cable.



**Root Causes:**

- ✓ Outdated as-built drawing of underground drainage pipeworks;
- ✓ waiver of issue of a work permit.

**Actions Taken Thus Far: Next Steps**

- ✓ Update as-built drawing of underground drainage pipeworks;
- ✓ retrain People on the use of a work permit system.